

# Starfrit

High precision scale  
Balance de précision  
Balanza de precisión

P.2  
P.9  
P.15



**INSTRUCTIONS  
MODE D'EMPLOI  
INSTRUCCIONES DE USO**

# INSTRUCTIONS FOR USE AND CARE

(Read the instructions before use)


## FEATURES / SPECIFICATIONS

- High precision strain gauge sensor
- Piece counting mode
- Blue LCD backlight
- Zero/Tare
- Low battery/Overload indicator
- Auto zero/Auto off

## BATTERIES


2 x 3V CR2032 lithium batteries or  
2 x AAA (1.5V) batteries (included)

## TO REPLACE BATTERIES



- 1 Open the battery compartment located on the bottom of the scale.
- 2 Take out the used battery (with the aid of a sharp object if needed)
- 3 Install new battery in the compartment, making sure to observe the polarity.


## LCD



## UNIT, MAX. CAPACITY AND DIVISION


Max. capacity	100 g / 3.5 oz / 64 dwt / 3 ozt
Division	0.01 g / 0.0005 oz / 0.01 dwt / 0.0005 ozt

## TO OPERATE




- 1 Place the scale on a solid, flat surface. Avoid carpet or other soft surfaces.
- 2 Press and release ON/OFF button to switch on the unit.
- 3 Wait until display prompts to *0.00* before starting weighing.
- 4 Always place the object to weight in the center of the platform.

## TO CHANGE THE UNIT OF WEIGHT MEASUREMENT



You can press UNIT button to toggle the weight measure between gram, ounce, dwt, ozt and to pre-set piece counting mode.

## PIECE COUNTING MODE



1 Press UNIT to select piece counting mode 'PCS' when the scale is vacant. The scale is programmed with 3 different pre-set quantities: 25 pcs, 50 pcs and 100 pcs.

2 Press UNIT for 3 seconds to select the desired pre-set quantity value (25, 50 or 100). Rapidly pressing UNIT will cycle through the pre-sets. Once a pre-set quantity is selected (for example 50), place this same quantity (50 pcs) on the weighing platform, and wait for LCD to flash '50'. The scale now recognizes this weight as the weight of 50 pcs, and also calculates and stores in memory the average single unit weight value.


3 Next time weighing a different quantity of this same object, simply turn on the scale and place X quantity of the object onto the weighing platform. LCD will start by showing the weight as usual. Press 'UNIT' to switch to piece counting mode 'PCS' and the LCD will display the quantity placed on the platform.

**Remark:** Repeat the above steps when conducting piece count calculations for different objects. For calibration accuracy, pre-set quantity of 100 pcs is suggested. An object with a unit weight of less than 1 scale division will not be calibrated.


## "ZERO" OR "TARE" FUNCTION

To weigh different loads consecutively without removing loads from the scale, put the first load on the scale to obtain a weight reading. Press Z/T button to reset the LCD reading to "0.00" before adding next load. You can repeat this operation.

By pressing Z/T, you can see the total weight of all loads on the scale. If you want to weigh more loads, just press Z/T to reset LCD reading to "0.00" again.




## LCD BACKLIGHT




- 1 LCD backlight will be activated when you switch on the scale. Backlight will automatically shut off after idling for 30 seconds.
- 2 Backlight will light up again whenever scale is re-activated

## AUTO SHUT OFF




Auto shut-off occurs if display shows '0' or shows the same weight reading for 2 minutes.

## MANUAL SHUT OFF




To maximize battery life, always press ON/OFF to turn off the scale after use.

## WARNING INDICATORS



1. Indicates Low battery power. Replace new battery.
2. Indicates scale over load. Remove the object to avoid damage. Maximum weight capacity of the scale is 0.5kg.

## TO OPEN THE COVER



## CLEANING AND CARE

- Clean the scale with a slightly damp cloth. DO NOT immerse the scale in water or use chemical/abrasive cleaning agents.
- The scale is high precision device. It is delicate built and extremely sensitive. Please avoid dropping the unit or subject the unit to violent impact which will damage it.

SUBSCRIBE TO THE NEWSLETTER  
TO LEARN MORE ABOUT OUR PROMOTIONS!

[www.Starfrit.com](http://www.Starfrit.com)



[www.facebook.com/starfrit](http://www.facebook.com/starfrit)



PRINTED IN CHINA FOR : ATLANTIC PROMOTIONS INC. LONGUEUIL (QUÉBEC) J4G 1V6  
CUSTOMER SERVICE : 1-800-361-6232 / MTL AREA : (514) 871-1095